



**Vessel Name: M/V "SUPERSTAR VIRGO"**

**PAGE 1 OF 7**

**Service Date: 27<sup>th</sup> Sep, 2014**

**Subject: The Contrast of those Cylinders (on-board) Bottom Condition**

**BEFORE & AFTER the Refurbishment**





**Vessel Name: M/V "SUPERSTAR VIRGO"**

**PAGE 2 OF 7**

**Service Date: 27<sup>th</sup> Sep, 2014**

**Subject: The Contrast of those Cylinders (on-board) Body Condition**

**BEFORE & AFTER the Refurbishment (cont'd)**





**Vessel Name: M/V “SUPERSTAR VIRGO”**

**PAGE 3 OF 7**

**Service Date: 27<sup>th</sup> Sep, 2014**

**Subject: The Contrast of those Cylinders (in Workshop) Body Condition**

**BEFORE & AFTER the Refurbishment**





Vessel Name: M/V "SUPERSTAR VIRGO"

PAGE 4 OF 7

Service Date: 27<sup>th</sup> Sep, 2014

Subject: The Contrast of those Cylinders (in Workshop) Body Condition

BEFORE & AFTER the Refurbishment (cont'd)



**AFTER** the Refurbishment Work





Vessel Name: M/V "SUPERSTAR VIRGO"

PAGE 5 OF 7

Service Date: 27<sup>th</sup> Sep, 2014

Subject: The Contrast of those Cylinders (in Workshop) Body Condition

**AFTER** the Refurbishment Work (cont'd)





Vessel Name: M/V "SUPERSTAR VIRGO"

PAGE 6 OF 7

Service Date: 27<sup>th</sup> Sep, 2014

Subject: The Contrast of those Cylinders (in Workshop) Bottom Condition

BEFORE the Refurbishment



AFTER the Refurbishment Work





**Vessel Name: M/V "SUPERSTAR VIRGO"**

**PAGE 7 OF 7**

**Service Date: 27<sup>th</sup> Sep, 2014**

**Subject: The Contrast of those Cylinders (in Workshop) Bottom Condition (cont'd)**

**BEFORE the Refurbishment**



**AFTER the Refurbishment Work**

