

FAX: (852) 2393 3443

E-MAIL: borsumy_fire@yahoo.com.hk main@borsumyfire.com.hk

PAGE 1 OF 4

Vessel Name: M/V "SEATTLE EXPRESS"

Service Date: 24th Jan, 2015

<u>Subject: Dismantled & mantled, cleaned-up and tested Main Distribution Valves for Engine Room & </u>

Cargo Holds 1 to 9

- Main Distribution Valves For Engine Room











FAX: (852) 2393 3443

E-MAIL: borsumy_fire@yahoo.com.hk main@borsumyfire.com.hk

Vessel Name: M/V "SEATTLE EXPRESS"

PAGE 2 OF 4

Service Date: 24th Jan, 2015

<u>Subject: Dismantled & mantled, cleaned-up and tested Main Distribution Valves for Engine Room & Cargo Holds 1 to 9</u>

- Main Distribution Valves For Cargo Holds 1 to 9







FAX: (852) 2393 3443

E-MAIL: borsumy_fire@yahoo.com.hk main@borsumyfire.com.hk

Vessel Name: M/V "SEATTLE EXPRESS" PAGE 3 OF 4

Service Date: 24th Jan, 2015

Subject: Dismantled & mantled, cleaned-up and tested Main Distribution Valves for Engine Room &

Cargo Holds 1 to 9

- Main Distribution Valves For Cargo Holds 1 to 9 (In Close Position)















FAX: (852) 2393 3443

E-MAIL: borsumy_fire@yahoo.com.hk main@borsumyfire.com.hk

Vessel Name: M/V "SEATTLE EXPRESS" PAGE 4 OF 4

Service Date: 24th Jan, 2015

Subject: Dismantled & mantled, cleaned-up and tested Main Distribution Valves for Engine Room &

Cargo Holds 1 to 9

- Main Distribution Valves For Cargo Holds 1 to 9 (In Open Position)









