

Rm 03, 11/F, Wang Yip Industrial Building, No. 1 Elm St., Taikoktsui, KLN, HONG KONG TEL: (852) 2392 5142, 2393 3315 FAX: (852) 2393 3443 E-MAIL: borsumy_fire@yahoo.com.hk main@borsumyfire.com.hk

Vessel Name: M/V "UNI PRUDENT" PAGE 1 OF 3

Date: 5th May, 2015

<u>Subject: Dismantled & mantled, cleaned-up and tested Three Main Distribution Valves for Main Engine</u>
<u>Room, Purifier Room and Cargo Holds 1 to 4</u>

- Main Valve for Main Engine Room















Rm 03, 11/F, Wang Yip Industrial Building, No. 1 Elm St., Taikoktsui, KLN, HONG KONG TEL: (852) 2392 5142, 2393 3315 FAX: (852) 2393 3443 E-MAIL: borsumy_fire@yahoo.com.hk main@borsumyfire.com.hk

Vessel Name: M/V "UNI PRUDENT" PAGE 2 OF 3

Date: 5th May, 2015

<u>Subject: Dismantled & mantled, cleaned-up and tested Three Main Distribution Valves for Main Engine</u> <u>Room, Purifier Room and Cargo Holds 1 to 4</u>

- Main Valve for Purifier Room











Rm 03, 11/F, Wang Yip Industrial Building, No. 1 Elm St., Taikoktsui, KLN, HONG KONG TEL: (852) 2392 5142, 2393 3315 FAX: (852) 2393 3443 E-MAIL: borsumy_fire@yahoo.com.hk main@borsumyfire.com.hk

Vessel Name: M/V "UNI PRUDENT" PAGE 3 OF 3

Date: 5th May, 2015

<u>Subject: Dismantled & mantled, cleaned-up and tested Three Main Distribution Valves for Main Engine</u> <u>Room, Purifier Room and Cargo Holds 1 to 4</u>

- Main Valve for Cargo Holds 1 to 4









